

## HKS700E SERVICE LETTER

### SL-700-003

**Subject:**

Running modification on HKS700E engine.

**Engine affected:**

HKS700E from S/N 101245

**Instruction:**

Introduction of new CDI UNIT. (see Fig 1)

The new CDI UNIT is interchangeable for old CDI UNIT.




Fig 1

June 2007

HKS AVIATION CO.,LTD

SL-700-003  
Page 1 of 1